




Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /  
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /  
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /  
 Nadomestni deli / Резервни части / Zapczęści / Części Zapasowe / Piese de schimb /  
 Rendelhető alkatrészek / Запасні частини / Reservní deloví / Резервни делови /  
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervnyj daju







XX = AA, GN, ...

Pos.	Part No.		
1	A 861 521 XX	7	A 964 520 NU
2	A 861 417 XX	8	A 962 370 NU
3	A 861 397 NU		B 960 364 NU
4	A 961 855 NU	9	A 961 172 NU
5	B 961 383 XX	10	B 960 900 XX
6	A 861 227 XX	11	A 961 230 XX

A7025/A7027



P	50°C	15°C	4	3	2	1	0
			°C	°C	°C	°C	°C
0,3 MPa	65°C	15°C	27	33	41	48	50
3 bar	85°C	15°C	33	42	53	63	65
			41	53	68	83	85




Ideal Standard

## CONNECT AIR

A 7007 .. A 7010 .. A 7012 .. A 7014 ..  
 A 7015 .. A 7018 .. A 7025 .. A 7027 ..

0321 / A 868 878  
 Made in Germany



Ideal Standard International NV  
 Corporate Village - Gent Building  
 Da Vincilaan 2  
 1935 Zaventem  
 Belgium

www.idealstandardinternational.com

